

DISTRICTWIDE RECOMMENDATIONS

The following recommendations are made on a districtwide basis and include each school or facility where applicable.

1. Correct deficiencies relating to safety to life, health, and sanitation as identified in the comprehensive Safety Inspection Report pursuant to §4.4(1), §5(1), and §5(13), SREF 2014.
2. Necessary modifications for the physically disabled in existing buildings recommended for continued use as provided for in §255.21, F.S.
3. Additional, or replacement of, equipment for existing school buildings recommended for continued use as provided in §2.1(9)(e), SREF 2014.
4. Replacement of roofs at existing facilities as provided in §1.2(55) and §4.1(1)(c), SREF 2014.
5. Provide storage, custodial spaces, and sanitation facilities to serve students, staff, and the general public as provided in §6.1, SREF 2014, and §423.20, FBC.
6. Provide paved auto parking areas pursuant to §5.2(f)10, SREF 2014, and §423.10.2.7, FBC.
7. Purchase sites for educational and ancillary facilities for future use beyond the projection period of this survey pursuant to §1.4, SREF 2014.
8. Retrofit existing schools for technology, which may include the creation, or improvement of, cable distribution points (closets in telephone parlance). Provide “clean power” and convenient access to video, data, and voice signal wiring, the built-in equipment involved in distributing video, data, and voice signals pursuant to §5, SREF 2014. This recommendation does not include new construction, remodeling, or terminal equipment (workstations, terminals, receiving equipment, and similar items).

The cost estimates for these districtwide recommendations are not included in the section on Financing the Proposed Program.