Change Order

Michael Martin

(Typed name)

| CHANGE ORDER NUMBER: 008 | OWNER: ⊠ |
|--|---|
| DATE: February 04, 2020 | |
| | ARCHITECT: ⊠ |
| ADCUITECTIC DOG IFOT AN MADER. 17 | CONTRACTOR: ⊠ |
| | 076 FIELD: □ |
| | oTHER: |
| CONTRACT FOR. General Construction | in One. |
| ed amount attributable to previously exec | uted Construction Change Directives) 3) days due to adverse weather (attached) |
| rder was this Change Order in the amount of | \$ <u>29,338,300.00</u> \$ <u>(546,176.86)</u> \$ <u>28,792,123.14</u> \$ <u>(0.00)</u> \$ 28,792,123.14 |
| nree (3) days. | |
| ede the Construction Change Directive. | Time or Guaranteed Maximum Price which have been eed upon by both the Owner and Contractor, in which |
| | |
| Culpepper Construction. | The School District of Santa Rosa County |
| | OWNER (Firm name) |
| | 5086 Canal Street |
| | Milton, FL 32570 ADDRESS |
| aller I | ADDITEO . |
| BY (Signature) | BY (Signature) |
| | ARCHITECT'S PROJECT NUMBER: 176 CONTRACT DATE: August 13, 2019 CONTRACT FOR: General Construction NS: ed amount attributable to previously exection change order in the amount of three (3) Change Orders reder was this Change Order in the amount of the date of this Change Order therefore is the date of this Change Order therefore is the changes in the Contract Sum, Contract tive until the cost and time have been agrised the Construction Change Directive. CHITECT, CONTRACTOR AND OWNER Culpepper Construction. CONTRACTOR (Firm name) 1538 Metropolitan Blvd. Tallahassee, FL 32308 ADDRESS |

Mr. Andrew Green

(Typed name)

Tim Wyrosdick, Supt of Schools

(Typed name)

DATE

Elkhart Drive K-8 School, Navarre, FL Weather Delay Log January 2020

As shown in the attached data, we experienced impacts to critical path activities due to rain this month. We have also included daily logs showing days when the project remained partially productive despite the rain. There were a total of ten (10) days of rain in January, compared to the average of six (6) per the attached NOAA data.

The rainfall on January 2-3 delayed activity S3-1010 Load Bearing CMU for Sequence 3 (Area B) and S3-1030 Erect Structural Steel. The overnight rain from January 14-15 slowed progress for S2-1010 Load Bearing CMU for Sequence 2 (Area A – Elevator Shaft) and the rain on January 29 has delayed S5-1010 Load Bearing CMU and S5-1030 Erect Structural Steel (both in Sequence 5 Area D&E)

As a result of this rainfall we are requesting three (3) weather days be added to the contract schedule.

38 Metropolitan Blvd / Tallahassee, FL 32308

CULPEPPER

| Year | Jan | Feb | Mar | Apr | May | Jun | Jul | Aug | Sep | Oct | Nov | Dec | Annual |
|------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|
| 2000 | 5 | 3 | 6 | 4 | 2 | 7 | 1 | 5 | 9 | 2 | 8 | 5 | 57 |
| 2001 | 4 | 4 | 11 | 2 | 2 | 8 | 9 | 10 | 3 | 2 | 3 | 3 | 61 |
| 2002 | 7 | 3 | 5 | 3 | 4 | 6 | 16 | 9 | 5 | 10 | 5 | 6 | 79 |
| 2003 | 1 | 9 | 10 | 4 | 5 | 18 | 14 | 13 | 6 | 4 | 6 | 5 | 95 |
| 2004 | 4 | 9 | 2 | 5 | 2 | 15 | 14 | 8 | 5 | 4 | 11 | 5 | 84 |
| 2005 | 5 | 8 | 9 | 9 | 4 | 8 | 7 | 16 | 4 | 0 | 5 | 6 | 81 |
| 2006 | 6 | 3 | 1 | 5 | 5 | 2 | 5 . | 9 | 7 | 4 | 2 | 5 | 54 |
| 2007 | 7 | 4 | 3 | 5 | 2 | 5 | 12 | 4 | 7 | 9 | 3 | 7 | 68 |
| 2008 | 9 | 5 | 4 | 3 | 4 | 10 | 10 | 8 | 5 | 4 | 4 | 5 | 71 |
| 2009 | 6 | 4 | 8 | 3 | 8 | 4 | 9 | 12 | 8 | 8 | 5 | 12 | 87 |
| 2010 | 7 | 8 | 8 | 3 | 6 | 11 | - 6 | 15 | 2 | 2 | 8 | 3 | 79 |
| 2011 | 6 | 5 | 3 | 1 | 3 | 2 | 7 | 6 | 7 | 1 | 4 | 6 | 51 |
| 2012 | 5 | 4 | 6 | 4 | 5 | 7 | 9 | 17 | 3 | 2 | 2 | 6 | 70 |
| 2013 | 5 | 11 | 2 | 6 | 4 | 10 | 16 | 10 | 7 | 3 | 4 | 5 | 83 |
| 2014 | 7 | 6 | 6 | 8 | 4 | 9 | 9 | 3 | 8 | 4 | 4 | 9 | 77 |
| 2015 | 4 | 7 | 3 | 10 | 8 | 9 | 11 | 8 | 6 | 4 | 5 | 10 | 85 |
| 2016 | 10 | 3 | 9 | 5 | 3 | 10 | 11 | 12 | 4 | 0 | 3 | 7 | 77 |
| 2017 | 8 | 3 | 5 | 5 | 10 | 19 | 11 | 12 | 4 | 7 | 0 | 8 | 92 |
| 2018 | 5 | 8 | 5 | 5 | 7 | 10 | 10 | 8 | 13 | 3 | 11 | 13 | 98 |
| 2019 | 6 | 5 | 2 | 5 | 4 | 7 | 8 | 12 | 0 | 10 | 3 | М | М |
| Mean | 6 | 6 | 5 | 5 | 5 | 9 | 10 | 10 | 6 | 4 | 5 | 7 | 76 |
| Max | 10 2016 | 11 2013 | 11 2001 | 10 2015 | 10 2017 | 19 2017 | 16 2013 | 17 2012 | 13 2018 | 10 2019 | 11 2018 | 13 2018 | 98 2018 |
| Min | 1 2003 | 3 2017 | 1 2006 | 1 2011 | 2 2007 | 2 2011 | 1 2000 | 3 2014 | 0 2019 | 0 2016 | 0 2017 | 3 2010 | 51 2011 |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Gulf | Breeze FL 32 |
|--|--|---|---------------------------------|--|--------------|
| DAY: | Thursday, January 2, 2020 | | 1052 | | |
| WEATHER: | Overcast am; rain pm | TEMP AM: | 66 | TEMP PM: | 69 |
| RAIN AMOUNT: | 0.375 | WEATHER DELAY?: | ☑Check if Weather Delay) | TEMP PM. | 09 |
| WORK DEDE | ODUED TODAY | | | | |
| THE RESERVE OF THE PARTY OF THE | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| Dayside. 100til | ngs in D columns in C | | | Culpepper Construction | 2 |
| Duch Massau | lada biritir di ni n | | | Bayside Structures | 13 |
| bush Masonry: | Laying block in stairwell in B u | ntil delayed by rain in afterno | oon | Bush Masonry | 7 |
| MM | | | | ммі | 7 |
| followed by ba | ound plumbing at cafeteria ar ckfill | nd "A"; inspection on under | ground plumbing in kitchen, | McKim & Creed | |
| Currier Dise | | | | J. Miller Construction | 4 |
| rain in afternoo | columns and beams at "B"; | finish roof decking partial i | n "A". Production slowed by | Branch Electrical | 3 |
| D | | | | Comfort Systems USA | |
| Branch: rough | in stairwell in section "B" | | | Larry M. Jacobs Testing | |
| I Millow Finish | and beauties at the state of the state of | | | Action Labor | |
| J.Miller: Finish | ed box installation at front dri | ve | | Sunrise | 8 |
| | | | | Foster | |
| | | | | ABG | |
| | | | | Knox Pest Control | |
| | | | | 0 | |
| | | | | 0 | |
| PROBLEMS | | | | 0 | |
| | of rain starting at 1 pm; brief sh | (1) (1) (1) (1) (1) (1) (1) (1) (1) (1) | | 0 | |
| Kain continued | l overnight; total of 3/8" accur | nulation by morning of 1/3 | | 0 | |
| | | | | 0 | |
| INSPECTION | | | | 0 | |
| County plumbing | g inspection of underground in | kitchenStructural steel; reba | r | 0 | |
| | | | | 0 | |
| DELIVERIES | S: | | | 0 | |
| | | | | 0 | |
| MERTHA | IVIO TO DO | | | 0 | |
| MEETINGS / | and the second s | | | 0 | |
| materproofing pr | e-install conference (Mike Mart | in, and rep from Arcadia | | 0 | |
| | | | | 0 | |
| Commence of the Commence of th | | | | TOTAL: | 44 |
| SUPERINTENDI | ENT'S SIGNATURE: | Stephen C. Feher | | | |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Gulf | Breeze FL 32 |
|--------------------|---|---|---------------------------------|--|--------------|
| DAY: | Friday, January 3, 2020 | | | | |
| WEATHER: | cloudy/ rain | TEMP AM: | 72 | TEMP PM: | 73 |
| RAIN AMOUNT: | 0.5 | WEATHER DELAY?: | ☑(Check if Weather Delay) | | |
| WORK PERF | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| Bayside:diggir | ng footings in section "D"; | placing rebar; strippoing form nd diamonds in cafeteria area | s in section "B" and "C" poured | Culpepper Construction | 3 |
| | | | a 32 yards of concrete | Bayside Structures | 17 |
| Bush: laying blo | ock in "B" section stairs rain | knocked off at 1 pm | | Bush Masonry | 7 |
| | | | | ммі | 7 |
| MMI:backfilling | g in kitchen area; undergro | ound in section "A" | | McKim & Creed | 0 |
| | | | | J. Miller Construction | 4 |
| J.Miller:rain kr | nocked off at 1 pm | | | Branch Electrical | 3 |
| | | | | Comfort Systems USA | 0 |
| Branch : under | rground piping in kitchen. | Rain knocked off at 1 pm | | Larry M. Jacobs Testing | 1 |
| | | | | Action Labor | 0 |
| Sunrise:Setting | g steel in section "B". Rain | Sunrise | 8 | | |
| | | | | Foster | |
| Jacobs testing | : tested concrete that was | poured today | | ABG | |
| | | | | Knox Pest Control | |
| | | | | 0 | |
| | | | | 0 | |
| PROBLEMS | | | | 0 | |
| | at 1 pm everyone knocked o | ff work | | 0 | |
| Got 1 / 2 " of ra | ain this weekend | | | 0 | |
| | | | | 0 | |
| INSPECTIO | | | | 0 | |
| Steve Leonard a | and County building inspecto | or inspected footings that were p | poured today | 0 | |
| | | | | 0 | |
| DELIVERIES | THE RESERVE AND ADDRESS OF THE PARTY OF THE | | | 0 | |
| received elevato | or pit rebar today | | | 0 | |
| | | | | 0 | |
| MEETINGS | / VISITORS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| | | | | TOTAL: | 50 |
| SUPERINTEND | ENT'S SIGNATURE: | Will Nichols | | | |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Gul | f Breeze FL 325 |
|-----------------------------|---------------------------|---------------------------|---------------------------------|---|-----------------|
| DAY: | Saturday, January 4, 2 | 020 | | | |
| WEATHER: | | TEMP AM: | | TEMP PM: | |
| RAIN AMOUNT: | 0.5 | WEATHER DELAY?: | Check if Weather Delay) | | |
| WORK PERF | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| | | | | Culpepper Construction | |
| | | | | Bayside Structures | |
| | | | | Bush Masonry | |
| | | | | ммі | |
| NO WORK | | | | McKim & Creed | |
| | | | | J. Miller Construction | |
| | | | | Branch Electrical | |
| | | | | Comfort Systems USA | |
| | | | | Larry M. Jacobs Testing | |
| | | | | Action Labor | |
| | | | | Sunrise | |
| | | | | Foster | |
| | | | | ABG | |
| | | | | Knox Pest Control | |
| | | | | 0 | |
| PROBLEMS | DELAYO. | | | 0 | |
| PROBLEMS | - DELATS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| INSPECTIO | NC. | | | 0 | |
| MOFECTIO | N3. | | | 0 | |
| | | | | 0 | |
| DELIVERIES | • 4 5 6 4 7 4 1 1 4 5 2 5 | MARKS TABLES AND A STREET | | 0 | |
| | 5. | | | 0 | |
| | | | | 0 | |
| MEETINGS | VISITORS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| | | | | TOTAL: | 0 |
| 相对的意思。在东 | AND THE PERSON NAMED IN | | | CONTRACTOR DESCRIPTION | |
| SUPERINTENDI | ENT'S SIGNATURE: | | | | |
| Alexandria (September 1988) | | EL MERCHANIA PERSONALION | 基础对反称的 种思想。20 | MENNING TO PROPERTY. | DESTRUCTION |



| 1220 - ELKH | ART K-8 | | Jobsite Phone: | 850-510-7703 | |
|-----------------------------------|---|--|--|--|----------------|
| | | | Jobsite Address: | 2535 Elkhart Drive, Gul | f Breeze FL 32 |
| DAY: | Monday, January 6, 202 | 0 | The second | | |
| WEATHER: | clear | TEMP AM: | 45 | TEMP PM: | 63 |
| RAIN AMOUNT: | 0.06 | WEATHER DELAY?: | Check if Weather Delay) | | |
| | | EBRADIS PALIS LES | LORE CONTRACTOR AND ADDRESS. | Control of the State of the Sta | |
| | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| Bayside: form stair: stripping | ed elevator footing; place g forms in "D" section | d rebar; and poured today; for | ming pockets in "B" section | Culpepper Construction | 3 |
| | | | | Bayside Structures | 17 |
| Bush: laying bl rain. | ock on "B" section stairs; la | ying block all in "B" section at do | puble wall. Start delayed by early | Bush Masonry | 7 |
| 12/22/21 2 | | | | ммі | 7 |
| MMI: undergro | ound in "A" section | | | McKim & Creed | 0 |
| | | | | J. Miller Construction | 4 |
| J.Miller: dug o compaction: b | out elevator pit pumped ou prought up to bottom of ele | it water and added gravel after evator footing bottom; then Bay | testing man checked for | Branch Electrical | 4 |
| | | | iside started | Comfort Systems USA | 2 |
| Branch: install | ling underground in kitche | n area | | Larry M. Jacobs Testing | 1 |
| | | | | Action Labor | 0 |
| Comfort: unloa | aded insulated piping that | connects from mechanical con | urtyard to mechanical room | Sunrise | 8 |
| | | | | Foster | |
| Jacobs: tesyte | ed concrete for elevator fo | oting | | ABG | |
| | | | | Knox Pest Control | |
| Sunrise: settin | g roof joist for section "B" oday and checked out are | a to start metal stude | | 0 | |
| | - and one of the out are | a to start metal statis | | 0 | |
| PROBLEMS | S - DELAYS: | | | 0 | |
| | | | | 0 | |
| Got 1 / 2 " of ra | ain over the weekend | | | 0 | |
| | | | | 0 | |
| INSPECTIO | | | | 0 | |
| Nova inspected | elevator pit for compaction | all approved | | 0 | |
| | | | | 0 | |
| DELIVERIE | | | | 0 | |
| | ited piping for mechanical | | | 0 | |
| | r cafeteria was delivered | today | | 0 | |
| MEETINGS | / VISITORS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| | | | | TOTAL: | 53 |
| | | 11.00 41 . 4 | Mary April Charles (1987) The Control of the Contro | 是这种的意思的 | VEG L |
| SUPERINTEND | ENT'S SIGNATURE: | Will Nichols | | | - 1 |
| | | | | | |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Gulf | Breeze FL 32 |
|--|--|---------------------------------|----------------------------------|--|--------------|
| DAY: | Monday, January 13, 20 | 20 | | | |
| WEATHER: | cloudy | TEMP AM: | 68 | TEMP PM: | 70 |
| RAIN AMOUNT: | 0.78 | WEATHER DELAY?: | Check if Weather Delay) | | |
| WORK PERF | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| Bayside: prep Left early because | ing slab area in kitchen; fause of rain. | orming beam on double block | walls between area "A" & "B". | Culpepper Construction | 3 |
| | | | | Bayside Structures | 18 |
| "A" & "B". Left | grout in stair area "D"; layin early because of rain. | g block at elevator and between | concrete columns between area | Bush Masonry | 7 |
| | | | | MMI | 4 |
| MMI: undergro | ound in area "A" | | | McKim & Creed | 0 |
| D1 | | | | J. Miller Construction | 0 |
| Branch: puttin | g in temporary lighting in | area "F" ; some underground in | n "B" | Branch Electrical | 5 |
| 0 | | | | Comfort Systems USA | 2 |
| Comfort: alggi | ing ditch for chilled water | ines from courtyard toward me | echanical area (about 80' long) | Larry M. Jacobs Testing | 1 |
| testine: second | | | | Action Labor | 00 |
| testing, sample | es of grout and mortar | | | Sunrise | 11 |
| Cuprice: instal | ling because and decision to | | | Foster | 2 |
| Sunrise, Instal | ling beams and decking it | area "A" and setting beams a | and columns in area "C" | ABG | 0 |
| Footon working | | | | Knox Pest Control | 1 |
| roster: working | g on framing in cafeteria | | | 0 | |
| | | | | 0 | |
| | S - DELAYS: | | | 0 | |
| Anemoon rain s | stopped concrete and maso | nry work. | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| INSPECTIO | NS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| DELIVERIE: | | | | 0 | |
| received a load | of structural steel; received | some light weight framing | | 0 | |
| | | | | 0 | |
| MEETINGS | / VISITORS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| STATE OF THE PARTY | THE RESIDENCE AND ADDRESS OF THE PARTY OF TH | | | TOTAL: | 54 |
| SUPERINTEND | ENT'S SIGNATURE: | Will Nichols | | | |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Gult | f Breeze FL 32: |
|---|--|--|---|---|-------------------|
| DAY: | Wednesday, January 15 | , 2020 | | | |
| WEATHER: | cloudy | TEMP AM: | 71 | TEMP PM: | 74 |
| RAIN AMOUNT: | | WEATHER DELAY?: | Check if Weather Delay) | 15mp Aug | |
| WORK PERF | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| forming pocke mechanical ro Bush: laying ble up mud around | ets and setting bolts in sta nom floor kitchen area nock at "D" area; laying block | ir "C" area; poured 7 column for k at elevator; laying foundation be ain to let work continue. 1/2 day | g concrete columns at "C" area; botings "D" area; they did pour plock in "E" section. Had to clean delay | Bayside Structures Bush Masonry MMI | 3 18 7 7 |
| | | uctures east side of "F" section | n | McKim & Creed J. Miller Construction Branch Electrical Comfort Systems USA | 2 4 5 |
| | in exterior metal stud wa | Larry M. Jacobs Testing Action Labor Sunrise | 0 11 | | |
| Sunrise: setting columns and beams "C" section Mckim & Creed: marked points for foundation walls "E" section Foster:walls in cafeteria area | | | | Foster ABG Knox Pest Control | 0 0 |
| Testing: tested | concrete for footings in " | D" area | | 0 | |
| received 1 inch | S - DELAYS: of rain last night o pour today there was a p | problem with the concrete pum | p so changed to tomorrow at 6 | 0 0 | |
| INSPECTIO | NS: | | | 0 | |
| DELIVERIE | S: | | 1 | 0 | |
| MEETINGS | / VISITORS: | | | 0 0 | |
| | | | | TOTAL: | 62 |
| SUPERINTEND | ENT'S SIGNATURE: | Will Nichols | | | |
| 的过程等点的是 创 | CONTRACTOR STATE | | | and Articological Section | |



| 1220 - ELKH | ART K-8 | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Guh | Breeze FL 32 |
|---|-------------------------|-------------------------------|---------------------------------|---|--|
| DAY: | Saturday, January 18, 2 | 020 | | | |
| WEATHER: | Rain | TEMP AM: | | TEMP PM: | Mary Villago |
| RAIN AMOUNT: | | WEATHER DELAY?: | ☑(Check if Weather Delay) | | |
| WORK PERF | ORMED TODAY: | | | WORK FORCE | |
| Sunrise - Nels | on Studs on C and B. U | nable to work most of day due | to rain. | WORK FORCE: | Crew Size: |
| | | | | Culpepper Construction | 1 |
| | | | | Bayside Structures | |
| | | | | Bush Masonry | |
| | | | | MMI | |
| | | | | McKim & Creed | |
| | | | | J. Miller Construction | |
| | | | | Branch Electrical | |
| | | | | Comfort Systems USA | |
| | | | | Larry M. Jacobs Testing | |
| | | | | Action Labor | |
| | | | | Sunrise | 5 |
| | | | | Foster | |
| | | | | ABG | |
| | | | | Knox Pest Control | |
| | | | | 0 | |
| PROBLEMS | - DELAYS: | | | 0 | |
| THE RESERVE OF THE PERSON NAMED IN COLUMN 1 | 0am due to rain | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| INSPECTIO | NS: | | | 0 | |
| NO. | | | | 0 | |
| | | | | 0 | |
| DELIVERIES | S: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| MEETINGS | VISITORS: | | | 0 | |
| | | | | | |
| | | | | 0 | |
| | | | | TOTAL: | 6 |
| SUPERINTEND | ENT'S SIGNATURE: | Stephen C. Feher | | | 200 Sept. 200 Se |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Guh | f Breeze FL 32 |
|--------------------|------------------------------|----------------------------------|---------------------------------|---|----------------|
| DAY: | Friday, January 24, 2020 |) | | | |
| WEATHER: | cloudy | TEMP AM: | 54 | TEMP PM: | 63 |
| RAIN AMOUNT: | 0.1875 | WEATHER DELAY?: | (Check if Weather Delay) | | |
| | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| Bayside: pour | ing 2nd floor of "B" wing; | forming columns at "D" wing; for | orming pier east end "D" wing | Culpepper Construction | 3 |
| Duchi Indian hi | | | | Bayside Structures | 24 |
| Bush: laying bi | ock at shear alls "A" area | | | Bush Masonry | 8 |
| MMI: roughin | alah at "O"i | | | ммі | 7 |
| MMI. roughin | slab at "C" wing | | | McKim & Creed | 0 |
| Branch: rough | in cheer wells #A# | | | J. Miller Construction | 0 |
| Branch, rough | iin shear walls "A" area; ro | ough in slab 2nd floor "A" area | | Branch Electrical | 5 |
| Comfort:hand | ing duct in patetoric areas | laying out for sleeves thru mas | | Comfort Systems USA | 3 |
| Comortinang | ing duct in caleteria area; | laying out for sleeves thru mas | sonary walls | Larry M. Jacobs Testing | 1 |
| Testing testin | g concrete for 2nd floor "E | 2" uéna | | Action Labor | 0 |
| resuring, testiri | g concrete for 2nd floor | s wing | | Sunrise | 10 |
| Sunrise: settin | g columns "D" section | | | Foster | 5 |
| odinise. sellin | g columns D section | | | ABG | 0 |
| Foster framin | g cafeteria area | | | Knox Pest Control | 0 |
| r oster. Iranimi | g caletella alea | | | 0 | |
| DDOD! FW | 2 251 41/2 | | | 0 | |
| PROBLEMS | S - DELAYS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| INCREATIO | NO. | | | 0 | |
| INSPECTIO | NS: | | | 0 | |
| | | | | 0 | |
| DEL N/EDIE | | | | 0 | |
| DELIVERIE | 5 : | | | 0 | |
| | | | | 0 | |
| MEETINGS | / VISITORS: | | | 0 | |
| MEETINGS | / VISITURS: | | | 0 | |
| | | | | 0 | |
| | | | | TOTAL: | 66 |
| SUPERINTEND | ENT'S SIGNATURE: | Will Nichols | | | |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Gulf Breeze FL 3 | |
|--------------------|------------------------|------------------|---------------------------------|--|------------|
| DAY: | Sunday, January 26, 20 | 20 | | | |
| WEATHER: | Rain | TEMP AM: | | TEMP PM: | |
| RAIN AMOUNT: | 0.125 | WEATHER DELAY?: | (Check if Weather Delay) | | |
| WORK PERF | ORMED TODAY: | | | MODY FORES | |
| (no work) | | | | WORK FORCE: | Crew Size: |
| | | | | Culpepper Construction | |
| | | | | Bayside Structures | |
| | | | | Bush Masonry | |
| | | | | MMI | |
| | | | | McKim & Creed | |
| | | | | J. Miller Construction | |
| | | | | Branch Electrical | |
| | | | | Comfort Systems USA | |
| | | | | Larry M. Jacobs Testing | |
| | | | | Action Labor | |
| | | | | Sunrise | |
| | | | | Foster | |
| | | | | ABG | |
| | | | | Knox Pest Control | |
| | | | | 0 | |
| DDOD! EWS | | | | 0 | |
| PROBLEMS | S - DELAYS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| INSPECTIO | NS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| DELIVERIES | S: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| MEETINGS | VISITORS: | | | 0 | |
| | | | | 0 | |
| | | | | 0 | |
| | | | | TOTAL: | 0 |
| SUPERINTENDI | ENT'S SIGNATURE: | Stephen C. Feher | | | |



| 1220 - ELKHART K-8 | | | Jobsite Phone: Jobsite Address: | 850-510-7703 2535 Elkhart Drive, Guit | f Breeze FL 32 |
|--------------------|--|------------------------------------|---------------------------------|---|----------------|
| DAY: | Wednesday, January 29 | , 2020 | 国主义员的 | | No. |
| WEATHER: | RAIN | TEMP AM: | 52 | TEMP ON | 50 |
| RAIN AMOUNT: | | WEATHER DELAY?: | ☑(Check if Weather Delay) | TEMP PM: | 52 |
| WORK PERF | ORMED TODAY: | | | WORK FORCE: | Crew Size: |
| Comfort: doing | DAY: MOST OF THE SU | t around 9am | | Culpepper Construction Bayside Structures Bush Masonry MMI McKim & Creed J. Miller Construction Branch Electrical Comfort Systems USA Larry M. Jacobs Testing Action Labor Sunrise Foster ABG Knox Pest Control | 5 3 |
| PPORI EM | S - DELAYS: | | | 0 | |
| | that the state of the second state of the seco | est of the day; not any productive | work today. | 0 0 | |
| INSPECTIO | NS: | | | 0 | |
| | | / | | 0 | |
| DELIVERIE | S: | | | 0 | |
| | | | | 0 | |
| MEETINGS | / VISITORS: | | | 0 | |
| | | | | 0 0 TOTAL: | 11 |
| SUPERINTEND | DENT'S SIGNATURE: | | | | |